

Inspection Photos

Location Name: CAERUS PICEANCE LLC HMR FEDERAL 18-11 (N18) Pad

Location #: 334933



Photo # 7536 From Entrance to location



Photo # 7537 From Entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC HMR FEDERAL 18-11 (N18) Pad

Location #: 334933




Photo # 7538 Location




Photo # 7539 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC HMR FEDERAL 18-11 (N18) Pad

Location #: 334933



Photo # 7540 Location



Photo # 7541 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC HMR FEDERAL 18-11 (N18) Pad

Location #: 334933



Photo # 7542 Location



Photo # 7543 Rupture disc vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: CAERUS PICEANCE LLC HMR FEDERAL 18-11 (N18) Pad

Location #: 334933



Aug 29, 2024 at 12:29:45 PM
CO

Photo # 7544 Rupture disc vent line does not comply with CECMC pressure safety device rules



Aug 29, 2024 at 12:29:59 PM
CO

Photo # 7545 Rupture disc vent line does not comply with CECMC pressure safety device rules