

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 7299 From Entrance to location

Photo # 7300 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 7301 Location



Photo # 7302 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 7303 Location

Photo # 7304 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069




Photo # 7305 Location



Photo # 7306 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 7307 Location



Photo # 7308 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 7309 Location



Photo # 7310 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 7311 Location



Photo # 7312 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 7313 Location



Photo # 7314 Open ended load line

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 7315 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 7316 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 7317 Sign laying on ground/not properly posted



Photo # 7318 Tank battery lacks signage

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 7319 Weeds in secondary containment



Photo # 7320 Weeds in secondary containment

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 7321 Weeds in secondary containment



Photo # 7322 Weeds in secondary containment

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 7323 Small amount of staining & debris