

Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 1-11C (I2SW) Pad

Location ID: 324349



Photo # 7164 From entrance to location



Photo # 7165 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC HMU 1-11C (I2SW) Pad
Location ID: 324349



Photo # 7166 Location



Photo # 7167 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 1-11C (I2SW) Pad

Location ID: 324349




Photo # 7168 Location



Photo # 7169 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 1-11C (I2SW) Pad

Location ID: 324349



Photo # 7170 Hole in liner/liner needs maintenance



Photo # 7171 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 1-11C (I2SW) Pad

Location ID: 324349



Photo # 7172 Flowline heating insulation open ended/available for entry by wildlife/wildlife hazard



Photo # 7173 Tank labels weathered & 1 label starting to peel