

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/26/2024

Submitted Date:

08/26/2024

Document Number:

695110182

**FIELD INSPECTION FORM**

Loc ID: 322089 Inspector Name: Beardslee, Tom On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10754  
Name of Operator: FOUR CORNERS ENERGY LLC  
Address: 500 DALLAS STREET #1650  
City: HOUSTON State: TX Zip: 77002

**Findings:**

- 9 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		JFulcher@bwenergyllc.com	
Labowskie, Steve		steve.labowskie@state.co.us	
		dgavito@americanhelium.us	
		jroberts@americanhelium.us	
		rhankins@americanhelium.us	
Demarco, Jaime		jdemarco@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208904	WELL	PR	01/01/2021	GW	033-06008	HUSKEY "B" UNIT 1	PR

**General Comment:**

<b>Location</b>			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	PHOTO 1: WELL SIGN/ COMPANY NAME POST ON LOCATION IS INACCURATE AND EMERGENCY CONTACT NUMBERS ARE INVALID.		
Corrective Action:	UPDATE EMERGENCY CONTACT PHONE NUMBER AS SOON AS POSSIBLE AND POST CURRENT OPERATOR NAME PER RULE 605.	Date:	10/26/2024
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		
Date: _____			
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	PHOTO 11 & 12: AREA ON IMPACTED SOIL NEAR PUMPJACK PRIME MOVER APPEARS TO BE FROM LEAKING PRIME MOVER.		
Corrective Action:	REPAIR EQUIPMENT, INCREASE Self-inspection, maintenance, and good housekeeping procedures and schedules PER RULE 1002..(2).D.	Date:	09/07/2024
Type	WEEDS		
Comment:	PHOTO 8 & 9: WEEDS NOT MAINTAINED ON AND INSIDE CRUDE OIL TANK BATTERY SECONDARY CONTAINMENT BERMS. PHOTO 10: WEEDS NOT MAINTAINED ON AND INSIDE PRODUCED WATER BATTERY SECONDARY CONTAINMENT BERMS.		
Corrective Action:	REMOVE WEEDS INCLUDING ON ALL SECONDARY CONTAINMENT BERMS PER RULE 606.	Date:	09/07/2024
Type	WEEDS		
Comment:	PHOTO 6: WEEDS NOT MAINTAINED AROUND LOCATION. PHOTO 7: WEEDS NOT MAINTAINED AROUND PUMPJACK.		
Corrective Action:	MAINTAIN WEEDS AROUND LOCATION PER RULE 606.	Date:	09/07/2024
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Gas Meter Run # 1			corrective date
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:	<input style="width: 100%;" type="text"/>		
Date: _____			
Type: Bird Protectors # 1			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		
Date: _____			

Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		37.611923,-104.993708
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 BBL	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	OTHER	STEEL AST		37.612375,-104.993587
Comment:	PHOTO 13: TANK IS VENTING FROM NEAR HATCH SEE ATTACHED FLIR VIDEO.				
Corrective Action:	Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. per Rule 608.a.(9).				Date: 08/28/2024

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	465 BBL	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 208904 Type: WELL API Number: 033-06008 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 12/12/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #700300286, THE CA FOR EMERGENCY CONTACT HAS NOT BEEN ADDRESSED, THE CA FOR METER CALIBRATION REPORT HAS BEEN ADDRESSED.	beardslt	08/26/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403902989	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684519">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684519</a>
695110198	FLIR VIDEO	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684496">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684496</a>