

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2024

Submitted Date:

08/27/2024

Document Number:

695110211

FIELD INSPECTION FORM

Loc ID 322094 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10754
Name of Operator: FOUR CORNERS ENERGY LLC
Address: 500 DALLAS STREET #1650
City: HOUSTON State: TX Zip: 77002

Findings:

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		JFulcher@bwenergyllaw.com	
,		irobets@americanhelium.us	
,		dnr_ecmc_engineering@state.co.us	
,		rhankins@americanhelium.us	
Demarco, Jaime		jdemarco@blm.gov	
Gavito, Danielle	303-524-4651	dgavito@americanhelium.us	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208950	WELL	SI	02/01/2022	GW	033-06055	SANTA FE CANYON FED 42-7	SI

General Comment:

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	PHOTO 1: WELL SIGN/ COMPANY NAME POST ON LOCATION IS INACCURATE AND EMERGENCY CONTACT NUMBERS ARE INVALID.		
Corrective Action:	UPDATE EMERGENCY CONTACT PHONE NUMBER AS SOON AS POSSIBLE AND POST CURRENT OPERATOR NAME PER RULE 605.	Date:	10/27/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	PHOTO 5: WEEDS AROUND LOCATION HAVE NOT BEEN MAINTAINED.		
Corrective Action:	MAINTAIN WEEDS PER RULE 606.	Date:	09/07/2024

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:	WELL HAS BEEN SHUT IN SINCE 2016		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		37.655166,-108.979584
Comment: CRUDE OIL TANK DO NOT HAVE PRESSURE RELIEF VALVE INSTALLED.					
Corrective Action: tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. per Rule 608.a.(9).					Date: 08/28/2024

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: CRUDE OIL TANK SHARE BERM WITH PRODUCED WATER TANK.				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 208950 Type: WELL API Number: 033-06055 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: WELL HAVE BEEN SHUT IN SINCE AUG. 2016 AND THERE IS NO MIT ON RECORD.

Corrective Action: Submitted Form 21, or Form 6 must be approved by the corrective action date for any wellbore not demonstrating current mechanical integrity. Wells demonstrating mechanical integrity must accomplish production without the use of mechanical intervention per rule 417.b. a 10 day notice via form 42 is required for all MIT'S Date: 09/07/2024

BradenHead

Date of Last Brhd Test: 12/12/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403902996	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684526
695110212	FLIR VIDEO	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684507
695110213	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684508