

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2024

Submitted Date:

08/27/2024

Document Number:

695110214**FIELD INSPECTION FORM**Loc ID 322118 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10506Name of Operator: SEELEY OIL COMPANY LLCAddress: PO BOX 1058City: CORTEZ State: CO Zip: 81321**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Demarco, Jaime		jdemarco@blm.gov	
Seeley, Nathaniel	(970) 565-2136	nathaniel@seeleyoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209013	WELL	SI	02/01/2020	OW	033-06118	SOUTHEAST SPARGO 1	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 8: UNUSED EQUIPMENT (3 2" RISERS NEAR COMPRESSOR). PHOTO 9: UNUSED EQUIPMENT (2 2" RISERS AND 1 1 3/4" RISER NEAR CRUDE OIL TANKS). PHOTO 10: UNUSED EQUIPMENT (1 3" RISER NEAR PRODUCED WATER TANKS). PHOTO 11: UNUSED EQUIPMENT (2 3" RISERS AND 1 2" RISER NEAR HEATED SEPARATOR). PHOTO 12: UNUSED EQUIPMENT (5 2" AND 1 1" RISERS NEAR HEATED SEPARATOR).		
Corrective Action:	REMOVE OR MARK RISERS FOR WHAT THEY CARRY (IE. WATER, GAS ECT.). PER RULE 606.	Date:	09/27/2024
Type	TRASH		
Comment:	PHOTO 13: TRASH (PEACE OF 3" POLLY PIPE NEAR PRODUCED WATER BATTERY).		
Corrective Action:	REMOVE ALL TRASH PER RULE 606	Date:	09/07/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	WELL HAVE BEEN SHUT IN SINCE 2016 METERS HAVE NOT BEEN CALIBRATED.		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	STEEL AST		37.578414,-108.997353
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	1000 GAL	STEEL AST		37.578154,-108.997540
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	CRUDE OIL SHARES SECONDARY CONTAINMENT WITH 2 400 BBLs PRODUCED WATER TANKS.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	209013	Type:	WELL	API Number:	033-06118	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>LAST MIT 8-2-22</div>									
Corrective Action: <div></div> Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #702500483, IT APPEARS THAT CA'S HAVE BEEN ADDRESSED HOWEVER THRE ARE NEW CORRECTIVE ACTION.	beardslt	08/27/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403902997	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684527
695110215	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684509