

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/03/2024

Submitted Date:

09/03/2024

Document Number:

717700294

**FIELD INSPECTION FORM**

Loc ID: 447050    Inspector Name: Burns, Adam    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10071  
Name of Operator: HIGHPOINT OPERATING CORPORATION  
Address: 555 17TH ST STE 3700  
City: DENVER    State: CO    Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447050	LOCATION	AC			-	Anschutz Equus Farms 3-62-4_5 NENE	AC

**General Comment:**

This is an audit on the tank battery

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Unmarked Risers in multiple spots need to be marked.		
Corrective Action:	Comply with the 1100 rules	Date:	12/31/2024
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Pits around the location need to have capacity labels.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	12/31/2024

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Compressor	# 1		
Comment:	Air Compressor		
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:	Line Heater		
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	#		

Comment: <a href="#">Flare Meter</a>			
Corrective Action:			Date:
Type: Other	#		
Comment: <a href="#">Gas lift risers</a>			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: VRU	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	#		
Comment: <a href="#">Slug Catcher</a>			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Flare	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	12	400 BBLs	STEEL AST		40.259700,-104.321100	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 447050 Type: LOCATION API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: Active Tank Battery

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a></p> <p>On Tuesday, August 27, 2024, at approximately 9:00 AM, Inspector Adam Burns conducted an on-site inspection at the following location:</p> <p>Location: Anschutz Equus Farms 3-62-4_5 NENE Tank Battery                      Operator: Civitas                      Location ID # 447050                      County: Weld</p> <p>During the inspection, a Tank Battery was observed. The following possible compliance issues were identified:                      Unmarked Risers: Unmarked Risers in multiple spots need to be marked Comply with the 1100 rules                      Capacity Labels: Pits around the location need to have capacity labels. Install sign to comply with Rule 605.h.                      A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules.                      Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</p>	burnsa	09/03/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717700295	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691133">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691133</a>