

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/03/2024

Submitted Date:

09/03/2024

Document Number:

717700310

FIELD INSPECTION FORMLoc ID 451928 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451926	WELL	SI	05/01/2024	OW	123-45303	Anschutz Equus Farms 4-62-33-6457CN	PR
451927	WELL	SI	04/01/2024	OW	123-45304	Anschutz Equus Farms 4-62-32-4148C	PR
451930	WELL	PR	08/26/2018	OW	123-45306	Anschutz Equus Farms 4-62-33-6457CSB	PR
451931	WELL	PR	03/18/2018	OW	123-45307	Anschutz Equus Farms 4-62-32-5764CN	PR
451932	WELL	PR	08/21/2018	OW	123-45308	Anschutz Equus Farms 4-62-33-4841C	PR
451935	WELL	PR	08/21/2018	OW	123-45310	Anschutz Equus Farms 4-62-33-4956C	PR

General Comment:[This is an audit on the wells](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action: Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 6		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: 451926	Type: WELL	API Number: 123-45303	Status: SI Insp. Status: PR
<u>Producing Well</u>			
Comment: PR			
Corrective Action:		Date:	
<u>BradenHead</u>			
Date of Last Brhd Test: 01/25/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0 Fluid Type: _____	
End Surf Csg Pressure: 0			
Comment: _____			
Corrective Action: _____		Date: _____	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 451927	Type: WELL	API Number: 123-45304	Status: SI Insp. Status: PR
<u>Producing Well</u>			
Comment: PR			
Corrective Action:		Date:	
<u>BradenHead</u>			
Date of Last Brhd Test: 01/31/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0 Fluid Type: _____	
End Surf Csg Pressure: 0			
Comment: _____			
Corrective Action: _____		Date: _____	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 451930	Type: WELL	API Number: 123-45306	Status: PR Insp. Status: PR
<u>Producing Well</u>			
Comment: PR			
Corrective Action:		Date:	
<u>BradenHead</u>			
Date of Last Brhd Test: 01/25/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0 Fluid Type: _____	
End Surf Csg Pressure: 0			
Comment: _____			
Corrective Action: _____		Date: _____	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 451931	Type: WELL	API Number: 123-45307	Status: PR Insp. Status: PR
<u>Producing Well</u>			
Comment: PR			
Corrective Action:		Date:	

BradenHead		
Date of Last Brhd Test:	01/31/2024	Annual Brhd Completed? Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:
	End Surf Csg Pressure: 0	
Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	451932	Type:	WELL	API Number:	123-45308	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well		
Comment:	PR	
Corrective Action:		Date:

BradenHead		
Date of Last Brhd Test:	01/25/2024	Annual Brhd Completed? Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:
	End Surf Csg Pressure: 0	
Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	451935	Type:	WELL	API Number:	123-45310	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well		
Comment:	PR	
Corrective Action:		Date:

BradenHead		
Date of Last Brhd Test:	01/25/2024	Annual Brhd Completed? Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:
	End Surf Csg Pressure: 0	
Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717700311	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691246