

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/03/2024

Submitted Date:

09/03/2024

Document Number:

717700312

FIELD INSPECTION FORM

Loc ID 451928 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451928	LOCATION	AC			-	Anschutz Equus Farms 4-62-32 SESE	AC

General Comment:

[This is an audit on the production equipment.](#)

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Location		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Unmarked Risers in multiple spots need to be marked.		
Corrective Action:	Comply with the 1100 rules.	Date:	12/31/2024

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	_____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment in multiple spots needs to be removed for good housekeeping.		
Corrective Action:	Comply with Rule 606	Date:	12/31/2024

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

Type:	#	Comment:	Corrective Action:	Date:	corrective date
Other		Gas lift risers			
Other		Unmarked Risers in multiple spots need to be marked.	Comply with the 1100 rules.	12/31/2024	
Bird Protectors	# 8				
Horizontal Heated Separator	# 7				
Horizontal Heater Treater	# 1	Line Heater			

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 451928 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: Active production equipment

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday, August 27, 2024, at approximately 9:25 AM, Inspector Adam Burns conducted an on-site inspection at the following location:</p> <p>Location: Anschutz Equus Farms 4-62-32 SESE Production Equipment Operator: Civitas Location ID # 451928 County: Weld</p> <p>During the inspection, an active location was observed. The following possible compliance issues were identified:</p> <p>Unused Equipment: Unused equipment in multiple spots needs to be removed for good housekeeping. Comply with Rule 606</p> <p>Unmarked Risers: Unmarked Risers in multiple spots need to be marked. Comply with the 1100 rules.</p> <p>A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules.</p> <p>Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</p>	burnsa	09/03/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717700313	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691317