

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/31/2024

Submitted Date:

09/03/2024

Document Number:

715200866**FIELD INSPECTION FORM**Loc ID 306873 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General	970-749-4139	sjninspections@ikavenergy.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271492	WELL	PR	08/01/2018	CBM	067-08931	LE PLATT B 1	PR

General Comment:

On 8/31/24 SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment.

During this inspection, the field inspector observed the water tank containment has been damaged. Attached photos show dual tire tracks leading up to and onto the steel ring containment. See CA in tank inventory

Location**Lease Road:**

Type	Access		
comment:	Gravel road off of CR 501		
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Stickers on containment for water tank. Sticker on separator and meter shed		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by gate at driveway entrance		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Metal panels around separator, meter shed and telemetry equipment		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Chain link fence around pumping unit and wellhead		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 1		corrective date
Comment:	Horizontal heated separator on east side of location		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Bird protector on separator stack		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Shores unit		
Corrective Action:		Date:	

Type: Bradenhead	# 1	
Comment:	Bradenhead access at surface	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	Meter run on south side of separator. Calibration shows 7/10/24	
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	C-66 Arrow gas engine	
Corrective Action:		Date:
Type: Ancillary equipment	# 4	
Comment:	Gas scrubber, day drum w/containment, telemetry equipment on south side of meter shed, cathodic protection riser on east side of water tank	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	BV STEEL		37.232300,-107.602310
Comment:	95bbl buried steel water tank on southeast corner of location				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient		Inadequate
Comment:	Steel ring containment. SE area field inspector conducted a field inspection regarding damage to the containment of the water tank. During the inspection, the field inspector observed dual tire tracks leading up to and onto the steel ring containment thus damaging the containment. The buried water tank was not damaged and the damage was limited to bending the containment for the water tank.			
Corrective Action:	Repair or replace the steel ring containment for the water tank			Date: 09/17/2024

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	271492	Type:	WELL	API Number:	067-08931	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well is PR at time of inspection								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	07/09/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	4	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200867	Location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691316