

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/30/2024

Submitted Date:

09/03/2024

Document Number:

715200862

FIELD INSPECTION FORMLoc ID 334002 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General	970-749-4139	sjninspections@ikavenergy.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301145	WELL	PR	05/09/2022	CBM	067-09691	GARY PATRICK 4	PR

General Comment:

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment.

Last field inspection equipment inventory was on 10/31/12
Equipment Inventory is for Gary Patrick 2&4 and Sparks B 2&4

Location

Lease Road:			
Type	Access		
comment:	Asphalt driveway off of SH 172 and gravel road to location entrance		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign at location entrance		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by fence at water tank. Stickers on separator sheds		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		
Produced Water	WELLHEAD	<= 1 bbl		
Comment:	Stuffing box is leaking. Stained soil around wellhead			
Corrective Action:	Remove and remediate stained soil in accordance with 912.c			Date: 09/30/2024

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Metal panels around separators, switchboard and water tank		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal panels around units, wellheads and control panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 4		
Comment:	4-Vertical gas separators in metal sheds on south side of location		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	4-Meter runs in metal separator sheds. Calibration shows 7/16/24		
Corrective Action:		Date:	

Type: Pump Jack	# 4	
Comment:	3-Linear rod pumps 1-Lufkin 320 for Sparks B 4	
Corrective Action:		Date:
Type: Prime Mover	# 4	
Comment:	4-Electric motors	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:	Bird protector on tank vent	
Corrective Action:		Date:
Type: Bradenhead	# 4	
Comment:	PVC bradenhead access for all wells	
Corrective Action:		Date:
Type: Ancillary equipment	# 3	
Comment:	Control panels, electric switchboard and telemetry equipment on east side of separators	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV STEEL		37.162140,-107.638250
Comment:	95bbl buried steel water tank with sump pump on southwest corner of location				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
067-09690
067-09692
067-09693
067-09691

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No		
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	301145	Type:	WELL	API Number:	067-09691	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well is PR at time of inspection								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	05/15/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			
		Paving	Pass			

Comment:

Access is partially paved with asphalt

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200880	location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691890