

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/28/2024

Submitted Date:

09/03/2024

Document Number:

713400284**FIELD INSPECTION FORM**Loc ID 335669 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10668Name of Operator: CAERUS ENERGY SERVICES LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Toews, Wesley		wtoews@blm.gov	
, CAERUS		cogcc.inspections@caerusoilandgas.com	

General Comment:**CECMC Inspection Report Summary**

On 8/28/2024 at approximately 13:14, Compliance Inspector Dusty Popejoy conducted an on-site inspection for a Frac operation at CAERUS PICEANCE LLC STORY GULCH UNIT-64S96W/26SENW at Location ID #335669 in Garfield County, Colorado. While there, I observed a remote frac operation pumping from STORY GULCH UNIT-64S96W/26SENW location to the BJU/M23A-496 pad.

During the inspection, the following compliance issues were observed:

Signs/Marker:

1- No labeling on Frac tank being used for a Diesel tank with a CA date of 10/3/2024

Limited inspection due to ongoing Frac operations on location.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Any Corrective Actions from previous Inspections are still applicable.

Location

Lease Road:			
Type	Access		
comment:	Access.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Sign at entrance to location.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Frac tank being used for a Diesel tank is not labeled. Spoke with Nick Croy on location at approximately 15:00 he told me he would get it labeled. Refer to photos		
Corrective Action:	Comply with CECMC Labeling rules.	Date:	10/03/2024

Emergency Contact Number:

Comment:	1-800-791-7691	
Corrective Action:		Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	Frac tank being used for a Diesel tank.		
Corrective Action:		Date:	
Type: Other	# 15		
Comment:	Frac tanks/Produced water		
Corrective Action:		Date:	
Type: Other	# 16		
Comment:	Frac pumps.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Diesel tank.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400285	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692021