

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/03/2024

Submitted Date:

09/03/2024

Document Number:

708904479

**FIELD INSPECTION FORM**

Loc ID: 335448 Inspector Name: Smelser, Wayne On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

35 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273049	WELL	PR	10/01/2021	GW	045-10208	FEDERAL RWF 14-18	PR
273051	WELL	PR	01/17/2005	GW	045-10211	FEDERAL RWF 314-18	PR
273052	WELL	PR	01/26/2005	GW	045-10212	FEDERAL RWF 11-19	PR
299225	WELL	PR	04/01/2024	GW	045-17624	FEDERAL RWF 313-18	PR
299226	WELL	PR	10/01/2022	GW	045-17625	FEDERAL RWF 413-18	PR
299264	WELL	PR	05/01/2018	GW	045-17628	FEDERAL RWF 414-18	PR
299265	WELL	PR	12/01/2014	GW	045-17629	FEDERAL RWF 514-18	PR
299266	WELL	PR	06/30/2010	GW	045-17630	FEDERAL RWF 324-18	PR
299267	WELL	PR	06/30/2010	GW	045-17631	FEDERAL RWF 21-19	PR
299268	WELL	PR	06/30/2010	GW	045-17632	FEDERAL RWF 321-19	PR
299269	WELL	SI	03/01/2024	GW	045-17633	FEDERAL RWF 421-19	SI
299270	WELL	PR	06/30/2010	GW	045-17634	FEDERAL RWF 521-19	PR
299271	WELL	PR	06/30/2010	GW	045-17635	FEDERAL RWF 621-19	PR
299272	WELL	PR	06/30/2010	GW	045-17636	FEDERAL RWF 311-19	PR
299273	WELL	PR	12/05/2012	GW	045-17637	FEDERAL RWF 411-19	PR
299277	WELL	PR	03/01/2023	GW	045-17638	FEDERAL RWF 511-19	PR

**General Comment:**

CECMC Inspection Report Summary

On 09/03/2024 at approximately 10:41 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad.

Location # 335448 in Garfield County Colorado.

Please refer to inspection 708903923 conducted on 05/29/2024, previous corrective actions have been completed.

Location is within High Priority/Density Habitat areas.

Location is approximately 315 yards from a creek/drainage that contributes to the Colorado River.

While there, I observed normal production operations.

This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:

Type	OTHER		
Comment:	Flameless gas infrared catalytic heater - hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:	Marked		
Corrective Action:		Date:	
Type: Plunger Lift	# 16		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Air compressor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Gas Meter Run	# 16		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Flameless gas infrared catalytic heater		
Corrective Action:		Date:	
Type: Bradenhead	# 16		
Comment:	Pressure transducers & Taylor plugs located on all bradenhead, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:	Tank equipped with telemetry					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		

Other (Capacity) 80 bbl	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	273049	Type:	WELL	API Number:	045-10208	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	273051	Type:	WELL	API Number:	045-10211	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	273052	Type:	WELL	API Number:	045-10212	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	299225	Type:	WELL	API Number:	045-17624	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	299226	Type:	WELL	API Number:	045-17625	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	299264	Type:	WELL	API Number:	045-17628	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	299265	Type:	WELL	API Number:	045-17629	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	299266	Type:	WELL	API Number:	045-17630	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

<b>Producing Well</b>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299267    Type: WELL    API Number: 045-17631    Status: PR    Insp. Status: PR

<b>Producing Well</b>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299268    Type: WELL    API Number: 045-17632    Status: PR    Insp. Status: PR

<b>Producing Well</b>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299269    Type: WELL    API Number: 045-17633    Status: SI    Insp. Status: SI

<b>Idle Well</b>			
Purpose:	<input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned                     Reminder: _____		
Comment:	Shut In Last produced February 2024		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299270    Type: WELL    API Number: 045-17634    Status: PR    Insp. Status: PR

<b>Producing Well</b>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299271    Type: WELL    API Number: 045-17635    Status: PR    Insp. Status: PR

<b>Producing Well</b>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299272    Type: WELL    API Number: 045-17636    Status: PR    Insp. Status: PR

<b>Producing Well</b>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299273    Type: WELL    API Number: 045-17637    Status: PR    Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 299277 Type: WELL API Number: 045-17638 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		Chemical tank containments
Waddles						
Check Dams						
		Sediment Traps				
Hydro Mulch						
Berms						
		Check Dams				
		Rip Rap				
Rip Rap						
		Compaction				Small amount of light compaction
Ditches						
Gravel						Sparse to none
		Ditches				
Compaction						Small amount of light compaction
		Gravel				Sparse to none

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904480	Inspection 708904479 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692120">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692120</a>
708904481	Inspection 708904479 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692121">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692121</a>