

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/04/2024

Submitted Date:

09/04/2024

Document Number:

717700388

FIELD INSPECTION FORM

Loc ID 444757 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444757	LOCATION	AC			-	Anschutz Equus Farms 4-62-28 NWSW	AC

General Comment:

[This is an audit on the production equipment](#)

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume			corrective date
Type: Bird Protectors	# 8				
Comment:					
Corrective Action:				Date:	
Type: Other	#				
Comment:	Unmarked riser, needs to be marked.				
Corrective Action:	Comply with the 1100 rules			Date:	12/31/2024
Type: Other	#				
Comment:	Gas lift riser				
Corrective Action:				Date:	
Type: Horizontal Heater Treater	# 1				
Comment:	Line Heater				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 7				
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 444757 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: active location

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday, August 27, 2024, at approximately 10:45 AM, Inspector Adam Burns conducted an on-site inspection at the following location:</p> <p>Location: Anschutz Equus Farms 4-62-28 NWSW Production Equipment Operator: Civitas Location ID # 444757 County: Weld</p> <p>During the inspection, an active location was observed. The following possible compliance issues were identified:</p> <p>Unmarked Risers: Unmarked riser, needs to be marked. Comply with the 1100 rules A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules.</p> <p>Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</p>	burnsa	09/04/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717700389	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692585