

Inspection Photos
Operator: Simcoe LLC
Location Name: Joe Martin 1
API: 05-067-06724



1. Location overview



2. Progressive cavity on wellhead

Inspection Photos
Operator: Simcoe LLC
Location Name: Joe Martin 1
API: 05-067-06724



3. Production equipment



4. Ancillary equipment

Inspection Photos
Operator: Simcoe LLC
Location Name: Joe Martin 1
API: 05-067-06724



5. Erosion on the south edge of location needs to be repaired