

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/18NENW

Location ID: 335996

Date: 8/29/2024



Southwest Corner of Location – Photo #03197



Wellheads – Photo #03201

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/18NENW

Location ID: 335996

Date: 8/29/2024



Aug 29, 2024 at 13:51:04
Parachute CO 81635
United States

Separators – Photo #03196



Aug 29, 2024 at 13:57:16
Parachute CO 81635
United States

Tank Battery – Photo #03209

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/18NENW

Location ID: 335996

Date: 8/29/2024



Heater Treater – Photo #03210



Location – Photo #03205

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/18NENW

Location ID: 335996

Date: 8/29/2024



Stored Supplies – Photo #03202



Insufficient Erosion Control – Photo #03206

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/18NENW

Location ID: 335996

Date: 8/29/2024



Insufficient Erosion Control/Damaged Fencing – Photo #03207



Transport of Sediment Off-Site – Photo #03198

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/18NENW

Location ID: 335996

Date: 8/29/2024



Transport of Sediment Off-Site – Photo #03199



Insufficient Erosion Control – Photo #03211