

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/03/2024

Submitted Date:

09/03/2024

Document Number:

696306693**FIELD INSPECTION FORM**Loc ID 424712 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10651Name of Operator: VERDAD RESOURCES LLCAddress: 1125 17TH STREET SUITE 550City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|---------------------------------|
| , | | Regulatory@verdadoil.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 430068 | WELL | SI | 03/01/2024 | OW | 123-36034 | Slick Rock 2-17-11-7-60 ST | SI |

General Comment:[This is a Well and Tank Battery Audit](#)

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | CONTAINERS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------|-------|--|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | Barbed Wire | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------|----------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |

| | | | | | |
|-------------------------------|-----|--------------------------|--|-------|--|
| Comment: | | Propane Tank- 500 Gallon | | Date: | |
| Corrective Action: | | | | Date: | |
| Type: Emission Control Device | # 1 | | | | |
| Comment: | | | | Date: | |
| Corrective Action: | | | | Date: | |
| Type: Prime Mover | # 1 | | | | |
| Comment: | | Gas Engine | | Date: | |
| Corrective Action: | | | | Date: | |
| Type: Vertical Separator | # 1 | | | | |
| Comment: | | | | Date: | |
| Corrective Action: | | | | Date: | |
| Type: Vertical Heater Treater | # 1 | | | | |
| Comment: | | | | Date: | |
| Corrective Action: | | | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | 400 BBLS | FIBERGLASS AST | | , |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|--------------------------------------|---------------------|-------------|-----------------------|
| | | | | | |
| Comment: | | Shares berm with the Crude Oil Tanks | | | |
| Corrective Action: | | Date: | | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 3 | 400 BBLS | STEEL AST | | 40.578870,-104.125430 |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

| | | | | | |
|------------------------|----------|------------------|-----------------|----------|-------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| <u>Venting:</u> | | | | | |
| Yes/No | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| <u>Flaring:</u> | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Inspected Facilities

Facility ID: 430068

Type: WELL

API Number: 123-36034

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: SI - Since 03.01.2024

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|---------------------|--------|------------|
| Routine Field Audit | petrie | 09/03/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696306694 | Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692986 |