

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/03/2024

Submitted Date:

09/04/2024

Document Number:

717300017

**FIELD INSPECTION FORM**

Loc ID 427868 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245729	WELL	PA		GW	123-13524	JAMES WEBSTER B 1	PA
427666	WELL	SI		OW	123-35066	HEIN 27-1	PA
442371	TANK BATTERY	AC	07/06/2015		-	HEIN TANK BATTERY 2-1	EG
487711	SPILL OR RELEASE	CL	08/28/2024		-	Webster James B 1/VY FAC Hist. Rel.	EG

**General Comment:**

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)  
[Photos uploaded](#)

**Inspected Facilities**

Facility ID: 245729 Type: WELL API Number: 123-13524 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 427666 Type: WELL API Number: 123-35066 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 442371 Type: TANK API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 487711 Type: SPILL OR API Number: - Status: CL Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

**ECMC Comments**

Comment	User	Date
Wells are plugged and abandoned (Hein 27-1); ECMC form 42 notice of start of plugging operations doc #403806037 received on 05/29/2024. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location dump and process flowlines at facility/ battery have been removed. Excavation/ remediation work is in progress - facility decommissioning nearing completion.	maclarej	09/04/2024
As outlined on COGCC form 19 spill report Doc #403903152 received on 08/29/2024: On August 27, 2024, historically impacted soil was discovered below the former produced water vessel (PWV) location following decommissioning activities at the WEBSTER JAMES B 1/VY Production Facility site. Excavation and assessment activities are ongoing. The affected infrastructure has been removed.	maclarej	09/04/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300018	Signage on location	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693189">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693189</a>
717300019	Fenced excavation at decom facility/ battery	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693190">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693190</a>
717300020	PA well area; view E to facility	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693191">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693191</a>