

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2024

Submitted Date:

09/04/2024

Document Number:

715200831**FIELD INSPECTION FORM**Loc ID 333442 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:18 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General	970-749-4139	sjninspections@ikavenergy.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284287	WELL	PR	08/01/2018	CBM	067-09137	GEORGE 11-11 3	PR

General Comment:SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

Location				
Lease Road:				
Type	Access			
comment:	Gravel road off of CR 510			
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Lease signs at location entrance			
Corrective Action:			Date:	
Type	TANK LABELS/PLACARDS			
Comment:	Metal sign by water tank. Stickers on separators			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>		Date:	<input type="text"/>
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	OTHER			
Comment:	Metal panels around telemetry on south side of meter sheds			
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:	Metal panels around wellhead and control panel			
Corrective Action:			Date:	
Type	TANK BATTERY			
Comment:	Metal panels around water tank, separators and meter sheds			
Corrective Action:			Date:	
Equipment:				
Type: Vertical Heated Separator	# 2			corrective date
Comment:	1-Vertical heated separator with metal shed for George 11-11 3 (west separator) 1-Vertical heated separator on west side of water tank (east separator)			
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:	Bird protectors on separator stacks			
Corrective Action:			Date:	

Type: Pump Jack	# 2	
Comment:	2-Linear rod pumps	
Corrective Action:		Date:
Type: Prime Mover	# 2	
Comment:	2-Electric motors	
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:	PVC bradenhead access for both wells	
Corrective Action:		Date:
Type: Deadman # & Marked	# 8	
Comment:	Not all deadmen are marked	
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date: 09/27/2024
Type: Gas Meter Run	# 2	
Comment:	2-Meter sheds by separators. Calibration shows 5/2/24	
Corrective Action:		Date:
Type: Ancillary equipment	# 4	
Comment:	2-control panels and 2-telemetry equipment	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV STEEL		37.209730,-107.692950
Comment:	95bbl buried steel water tank on east side of location				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above**AirsID**

API Number	API Number	AirsID
067-09137		
067-07686		

Venting:

Yes/No		
--------	--	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	284287	Type:	WELL	API Number:	067-09137	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well is PR at time of inspection								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	07/25/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Culverts	Pass			
Rip Rap	Pass					
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	115	1733133	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200896	location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693557