

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2024

Submitted Date:

08/29/2024

Document Number:

717700270**FIELD INSPECTION FORM**Loc ID 446992 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
,		Inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446990	WELL	PA	06/27/2019	OW	123-43430	Anschutz Equus Farms 3-62-4-2417C2	TA

**General Comment:**[This is an audit on the well and documents on file](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well name wrote on well doesn't reflect what is in the ECMC data base. Submit proper documentation and correct designated well sign.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 446990 Type: WELL API Number: 123-43430 Status: PA Insp. Status: TA

**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

**Comment:**

Well is T/A

Form 42 on file. Document #401709694

Form 6(S) on file. Document #402119115. Plug date shows 7/26/2018.

Well file documentation shows that the well was P/A in 2018 but appears to be T/A. To maintain compliance verify there is no gas leak on the well and the integrity of the well plugs. Once verified Cut and Cap Well.

Corrective Action: **Comply with Rule 434**

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<b>ECMC Inspection Report Summary</b>  On Tuesday, August 27, 2024, at approximately 8:45 AM, Inspector Adam Burns conducted an on-site inspection at the following location:  Well: Anschutz Equus Farms 3-62-4-2417C2 Operator: Civitas API: 05-123-43430 County: Weld Well is T/A Form 42 on file. Document #401709694 Form 6(S) on file. Document #402119115. Plug date shows 7/26/2018. During the inspection, a shut in well was observed. The following possible compliance issues were identified: Incorrect Well Name: Well name wrote on well doesn't reflect what is in the ECMC data base. Submit proper documentation and correct designated well sign. Install sign to comply with Rule 605.d. Well Abandonment: Well file documentation shows that the well was P/A in 2018 but appears to be T/A. To maintain compliance verify there is no gas leak on the well and the integrity of the well plugs. Once verified Cut and Cap Well. Comply with Rule 434 A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous inspections that have not been addressed remain applicable.	burnsa	08/29/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403905098	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6686735">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6686735</a>
717700271	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6686715">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6686715</a>