

Interim Reclamation and Stormwater Inspection

Date: 09/05/2024

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 318096

Inspection Document #: 708201581

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Elkhorn CO-62N67W 21 NENW

Location ID: 318096



Photos 1 & 2. Vehicle track out, originating from the tank battery, was observed for approximately 100 yards onto eastbound WCR 20.

Inspection Photos

Location Name: Elkhorn CO-62N67W 21 NENW

Location ID: 318096



Photos 3 & 4. Vehicle track out appears to have originated from the tank battery area, which does not appear to be properly stabilized to minimize erosion or prevent site degradation in accordance with Rule 1002.e.(1).

Inspection Photos

Location Name: Elkhorn CO-62N67W 21 NENW

Location ID: 318096



Photos 5 & 6. Photo 5 (left) and Photo 6 (right) taken from the tank battery area and WCR 20, respectively. Tire tracks appear to be similar to one another.

Inspection Photos

Location Name: Elkhorn CO-62N67W 21 NENW

Location ID: 318096



Photos 7 & 8. Trash was observed on the southern portion of the tank battery.

Inspection Photos
Location Name: Elkhorn CO-62N67W 21 NENW
Location ID: 318096



Photo 9. Trash observed on the eastern portion of the tank battery.

Inspection Photos
Location Name: Elkhorn CO-62N67W 21 NENW
Location ID: 318096



Photo 10. Stained soil observed near the northern vertical AST.

Inspection Photos
Location Name: Elkhorn CO-62N67W 21 NENW
Location ID: 318096



Photo 11. Trash/debris observed near the pumpjack at Well API 123-08391.