

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/28/2024

Submitted Date:

09/05/2024

Document Number:

709100368

FIELD INSPECTION FORM

 Loc ID 312143 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 52530
 Name of Operator: MAGPIE OPERATING INC
 Address: 2707 SOUTH COUNTY RD 11
 City: LOVELAND State: CO Zip: 80537
Findings:

- 6 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Warner, Ryan	720-233-0875	magpieoil@yahoo.com	All Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Chamard, Megan		megan.chamard@state.co.us	
Lindley, Trent		trent.lindley@state.co.us	
WARNER, JAMES	970-669-6308	jwarner105@gmail.com	Principal Agent
Dylan Edwardson		dylan.edwardson@state.co.us	
Trujillo, Aaron		aaron.trujillo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218853	WELL	PA	04/22/2019	OW	075-05621	WARNECKE 1	EI
312143	LOCATION	AC	04/22/2019		-	WARNECKE-68N53W 30SESE	EI

General Comment:

On August 28, 2024, ECMC Environmental Staff Krystal Heibel and Dylan Edwardson conducted an environmental field inspection of MagPie Operating Inc (MagPie) Warnecke (Location ID: 312143).

Weather was sunny, and temperature about 80 degrees Fahrenheit.
 Active Remediation Project #13484

Refer to the previous Final Reclamation and Stormwater Inspection; dated 02/07/2024; Doc #708200921

Refer to the photo-documentation of the observed compliance issues attached to this report. Any corrective action(s) and corrective action due dates from previous inspections that have not been addressed are still applicable.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris (e.g. plastic, wire) remains around the location. Refer to attached inspection photos.		
Corrective Action:	Comply with Rule 606 to remove all debris/trash from the location.	Date:	02/21/2024
Type	OTHER		
Comment:	During this inspection, Staff observed construction fencing around the perimeter of the open excavation.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 218853 Type: WELL API Number: 075-05621 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 312143 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Refer to the Reclamation and Stormwater Inspection (Doc# 708201566) for additional information.	heibelk	09/05/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100369	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6695236