

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8303 From Entrance to location




Photo # 8304 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8305 Location




Photo # 8306 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad
Location #: 334613



Photo # 8307 Location



Photo # 8308 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad
Location #: 334613



Photo # 8309 Location



Photo # 8310 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613




Photo # 8311 Location



Photo # 8312 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613




Photo # 8313 Unmarked deadman near SHIDELER FEDERAL 26-8C1 wellhead



Photo # 8314 Same unmarked deadman

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8315 Multiple holes in liner/liner needs maintenance



Photo # 8316 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8317 Multiple holes in liner/liner needs maintenance



Photo # 8318 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8319 Hole in liner/liner needs maintenance



Photo # 8320 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8321 Hole in liner/liner needs maintenance



Photo # 8322 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8323 Multiple holes in liner/liner needs maintenance




Photo # 8324 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8325 Multiple holes in liner/liner needs maintenance



Photo # 8326 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8327 Hole in liner/liner needs maintenance



Photo # 8328 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8329 Hole in liner/liner needs maintenance




Photo # 8330 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8331 Hole in liner/liner needs maintenance



Photo # 8332 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8333 Multiple holes in liner/liner needs maintenance



Photo # 8334 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8335 Multiple holes in liner/liner needs maintenance



Photo # 8336 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8337 Hole in liner/liner needs maintenance




Photo # 8338 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8339 Small amount of weeds in secondary containment



Photo # 8340 Small amount of weeds in secondary containment

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



Photo # 8341 Small amount of weeds in secondary containment



Photo # 8342 Small amount of weeds in secondary containment

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-12 (L25W) Pad

Location #: 334613



**Photo # 8343 Flowline heating insulation open ended
/available for entry by wildlife/wildlife hazard**