

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2024

Submitted Date:

08/29/2024

Document Number:

707603148

**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐

427120      Evins, Bret      2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER      State: CO      Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14      Number of Comments

1      Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428564	WELL	SI	06/01/2024	OW	123-35410	Schaefer 10E-223	SI

**General Comment:**

This is a WELL inspection.  
Well(s): 1: Shut-In | SI.  
Battery: Inactive | Shut-down.

Centralized Battery serves 1 Location ID  
(427120).  
(Well(s): 4: Shut-In | SI).

Centralized Battery serves 1 Tank Battery Facility ID  
(Pending).

Reference (Associated Well(s), Battery Inspections):  
A.) Field Inspection Report doc. #707603148 and/or Location ID #427120  
for SI Well(s), Corrective Action (CA) info.  
B.) Field Inspection Report doc. #707603150 and/or Location ID #427120  
for SI Well(s), Corrective Action (CA) info.  
C.) Field Inspection Report doc. #707603152 and/or Location ID #427120  
for SI Well(s) info.  
D.) Field Inspection Report doc. #707603154 and/or Location ID #427120  
for SI Well(s) info.  
E.) Field Inspection Report doc. #707603156 and/or Location ID #427120  
for Battery / Facility, Equipment info.

**Location****Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:	Wellsite: Paraffin Control. Placards.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel, barbed wire.		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellsite: 1: Paraffin Control pump, tank w/ drip containment. Placards.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor. Inactive   Shut-down.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Inactive   Shut-down.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.507655,-104.428029	
Comment:	Centralized Battery serves 1 Location ID (427120). (Well(s): 4: Shut-In   SI).  Centralized Battery serves 1 Tank Battery Facility ID (Pending).					
Corrective Action:					Date:	

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 428564 Type: WELL API Number: 123-35410 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITE

Comment: Shut-In | SI.  
ECMC records last prod: 05/2024.  
Locked-Out, Tagged-Out | LOTO.  
OOSLAT at well, separator: 08/08/2024.  
  
CORRECTIVE ACTION: see below.

Corrective Action: 1.) Well GPS coordinates are inaccurate per Form 5 Final Drilling Completion Report.  
See Doc. #400326858 dated: 10/18/2012.  
Refer to Rule 414.b.(2).F for guidance.  
\* Collect updated / accurate GPS coordinates at wellsite to comply with Rule 414.b.(2).F.  
& Rule 216. Report updated / accurate GPS coordinates on ECMC Form 4 Sundry  
Notice,  
Section "CHANGE OF LOCATION OR AS BUILT GPS REPORT."  
Corrective Action date: 09/30/2024.  
See photo #2.  
\* A follow up on this site inspection will be conducted to ensure that compliance issues  
have been corrected to comply with ECMC rules.

Date: 09/30/2024**BradenHead**Date of Last Brhd Test: 04/30/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0Comment: \_\_\_\_\_Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Completion**

Operation: \_\_\_\_\_

Date Flowback: \_\_\_\_\_

Contractor: \_\_\_\_\_

Comment: \_\_\_\_\_Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On TUE 08/27/2024 at approximately 13:48 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: Schaefer/NW-10 Pad Location ID: 427120 Well Name(s): Schaefer 10E-223. API: 123-35410. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In   SI. Battery: Inactive   Shut-down.</p> <p>During this inspection the following possible compliance issue(s) were observed: 1.) Well GPS coordinates are inaccurate per Form 5 Final Drilling Completion Report. See Doc. #400326858 dated: 10/18/2012. Refer to Rule 414.b.(2).F for guidance. * Collect updated / accurate GPS coordinates at wellsite to comply with Rule 414.b.(2).F. &amp; Rule 216. Report updated / accurate GPS coordinates on ECMC Form 4 Sundry Notice, Section "CHANGE OF LOCATION OR AS BUILT GPS REPORT." Corrective Action date: 09/30/2024. See photo #2.</p> <p>* A follow up on this site inspection will be conducted to ensure that compliance issues have been corrected to comply with ECMC rules.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	08/29/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403906466	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6688586">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6688586</a>
707603149	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6688579">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6688579</a>