

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2024

Submitted Date:

08/29/2024

Document Number:

714201584**FIELD INSPECTION FORM**Loc ID 476282 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	<a href="#">All Inspections</a>
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	<a href="#">all inspections.</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476282	LOCATION	AC			-	Musick-McClintock 3, 5	AC

**General Comment:**

This is an audit of MUSICK-MCCLINTOCK TANK BATTERY scout card and related documents followed by a field inspection.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	sign is damaged. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	09/12/2024
Type	TANK LABELS/PLACARDS		
Comment:	one tank appears to not display contents/capacity. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/12/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	overgrown vegetation on various areas of location. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	09/12/2024

Overall Good: ☐**Spills:**

Type	Area	Volume	
------	------	--------	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type		
Comment:		
Corrective Action:		Date:

**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	50 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with other tanks.				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)	UNKNOWN	
Other (Capacity)	UNKNOWN	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	476282	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	AC
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: EQUIPMENT ONSITE									
Comment: SI									
Corrective Action:      Date:									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input type="text"/>						Date: <input type="text"/>
Corrective Action: <input type="text"/>						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>WEATHER CONDITIONS: sunny, dry ground.</p> <p>On Thursday, August 29, 2024 at approximately 1130, I, Inspector Brittani Santistevan, conducted an on-site inspection at MUSICK-MCCLINTOCK TANK BATTERY (KP Kauffman Company Inc.), at location ID: 476282 in WELD COUNTY, Colorado.</p> <p>While there, I observed A SHUT IN FACILITY.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. It appears there is overgrown vegetation on various areas of location. Remove to comply with Rule 606. (Corrective Action Date: September 12, 2024) See attached photo #3-8.</p> <p>2. It appears the signage for the tank battery is damaged. Install sign to comply with Rule 605.e. (Corrective action Date: September 12, 2024) See attached photo #1.</p> <p>3. It appears the contents and capacity are no longer displayed on one tank. Install sign to comply with Rule 605.h. (Corrective Action Date: September 12, 2024) See attached photo #2.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	08/29/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403906470	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6688602">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6688602</a>
714201585	photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6688585">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6688585</a>