

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/28/2024

Submitted Date:

08/30/2024

Document Number:

693807688**FIELD INSPECTION FORM**Loc ID 316832 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10841Name of Operator: AMERICAN HELIUM OPERATING LLCAddress: 600 TRAVIS STREET SUITE 5050City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gavito, Danielle	303-524-4651	dgavito@americanhelium.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Demarco, Jaime		jdemarco@blm.gov	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264708	WELL	SI	06/01/2024	GW	113-06108	FOSSIL FEDERAL 4-20	SI

**General Comment:**

ECMC staff performed a routine field inspection on 8/28/2024.  
 Issues were found requiring corrective action. See inspection text and photos for details.  
 Any Corrective Actions from previous inspections that have not been addressed are still applicable.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action		Date:	
Type	Main		
comment:			
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign on meter housing		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/30/2024

Emergency Contact Number:

Comment: 435-631-2239

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Maintain weed control		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	1 Meter run Service for FOSSIL FEDERAL #6-19 API #05-113-06151 Approx 300' NW. See Inspection Doc # 693807699		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:	1 Separator Service for FOSSIL FEDERAL #6-19 API #05-113-06151 Approx 300' NW. See Inspection Doc # 693807699		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	100 BBLS	PBV STEEL		38.063485,-108.666082
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		38.063422,-108.666481
Comment:	Service for FOSSIL FEDERAL #6-19 API #05-113-06151 Approx 300' NW				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:								
Corrective Action:							Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS			
PRODUCED WATER	1	300 BBLs	STEEL AST		38.063370,-108.666109			
Comment:								
Corrective Action:							Date:	
<u>Paint</u>								
Condition								
Other (Content)								
Other (Capacity)								
Other (Type)								
<u>Berms</u>								
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance				
Comment:								
Corrective Action:							Date:	
<u>Venting:</u>								
Yes/No	NO							
Comment:								
Corrective Action:						Date:		
<u>Flaring:</u>								
Type								
Comment:								
Corrective Action:						Date:		

Inspected Facilities									
Facility ID:	264708	Type:	WELL	API Number:	113-06108	Status:	SI	Insp. Status:	SI

Idle Well

Purpose:

☒ Shut In

☐ Temporarily Abandoned

Reminder:

Comment:

Well shut in 4/2024

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test:

09/16/2023

Annual Brhd Completed?

Yes

Last Brhd Test Results

Initial Surf Csg Pressure:

80

Fluid Type:

NONE

End Surf Csg Pressure:

0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			
Gravel	Pass	Ditches	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403907228	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6689585">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6689585</a>
693807692	Inspection photos 8/28/2024	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6689573">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6689573</a>