

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/06/2024

Submitted Date:

09/06/2024

Document Number:

717300021

FIELD INSPECTION FORMLoc ID 305214 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275700	WELL	SI	10/01/2021	OW	123-22659	HOWARD 1-27	PA
417201	WELL	SI	10/01/2021	OW	123-31609	DRY CREEK FEDERAL 41-27	PA
417203	WELL	SI	10/01/2021	OW	123-31611	DRY CREEK 21-27	PA
482412	SPILL OR RELEASE	CL	06/22/2022		-	Howard1-27/UP42AM1 O SA Tank Bat.	EG
487709	SPILL OR RELEASE	CL	08/27/2024		-	HOWARD 1-27 UP42AM1 FAC Hist. Rel.	EG

General Comment:ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 275700	Type: WELL	API Number: 123-22659	Status: SI	Insp. Status: PA
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 417201	Type: WELL	API Number: 123-31609	Status: SI	Insp. Status: PA
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 417203	Type: WELL	API Number: 123-31611	Status: SI	Insp. Status: PA
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482412	Type: SPILL OR	API Number: -	Status: CL	Insp. Status: EG
---------------------	----------------	---------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 487709	Type: SPILL OR	API Number: -	Status: CL	Insp. Status: EG
---------------------	----------------	---------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
(3) wells are plugged and abandoned (Howard 1-27, Dry Creek 41-27, 21-27); COGCC form 42 notices of start of plugging operations received June 2024. On location WH flowlines have been removed. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location dump and process flowlines at facility/ battery have been removed. ECMC form 42 notice of flowline abandonment (removal) completed doc #403911382 received 09/05/2024. Fenced excavations observed at PA wells and tank battery/ equipment areas. No flowlines/ risers observed. Remediation work (historical) is in progress.	maclarej	09/06/2024
As outlined on COGCC form 19 spill report Doc #403900986 received on 08/27/2024: On August 26, 2024, historically impacted soil was discovered below the former produced water vessel (PWV) and dump line (DL) locations following decommissioning activities at the HOWARD 1-27 UP42AM1 Production Facility site. Excavation and assessment activities are ongoing. The affected infrastructure has been removed.	maclarej	09/06/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300022	Siganage on location	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6695854
717300023	Fenced excavation at PA well	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6695855
717300024	Fenced excavation at facility/ equipment area	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6695856