

Inspection Photos

Operator: Hilcorp Energy

Location Name: Huber Kaime 1-12U API: 067-07697

Location Name: Huber Kaime 3-12U API: 067-09237



1. Lease signs at southwest corner of location.
Landowner stored equipment on west side of location



2. West side of pumping units

Inspection Photos

Operator: Hilcorp Energy

Location Name: Huber Kaime 1-12U API: 067-07697

Location Name: Huber Kaime 3-12U API: 067-09237



3. Northeast corner of location looking southwest



4. South edge of location. Landowner is storing equipment along south side of location

Inspection Photos

Operator: Hilcorp Energy

Location Name: Huber Kaime 1-12U API: 067-07697

Location Name: Huber Kaime 3-12U API: 067-09237



5. North side of separators looking west. Misc equipment stored on west side of location



6. Erosion on access to location