

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2024

Submitted Date:

09/06/2024

Document Number:

715200820**FIELD INSPECTION FORM**Loc ID 334274 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**20 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General	713-209-4000	FarmingtonRegulatoryTechs@hilcorp.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216091	WELL	PR	07/01/2013	CBM	067-07697	HUBER-KAIME 1-12U	PR

General Comment:SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

Location

Lease Road:			
Type	Access		
comment:	Gravel road off of CR 510 across private ranch access		
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on separator		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign at location entrance		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			

Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Landowner is storing vehicles and misc debris on west and south edge of location. See attached photos		
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Metal cage around gear box		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Wire fence along north edge of location		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 2		
Comment:	Electric motors		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Not all deadmen are marked		

Corrective Action:	Install proper guy line markers per Rule 1003.a		Date:	09/27/2024
Type: Vertical Heated Separator	# 2			
Comment:	1-Vertical heated separator with metal shed and built in liquid storage on north side of location (East separator for Huber Kaime 1-12U) 1-Vertical heated separator with metal shed on north side of location. (West separator for Huber Kaime 3-12U)			
Corrective Action:			Date:	
Type: Compressor	# 0			
Comment:	Compressor removed from location. Compressor shed still on location at time of inspection			
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:	Bird protector on separator stacks			
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	PVC bradenhead access for both wells			
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:	American 114 for Huber Kaime 1-12U. Lufkin 320 for Huber Kaime 3-12U			
Corrective Action:			Date:	
Type: Ancillary equipment	# 3			
Comment:	Electric panel, control panel and phase convertor on southeast corner of location. Telemetry equipment at separator			
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:	1-Meter run in metal separator shed for Huber Kaime 1-12U. Calibration shows 8/12/24 1-Meter run for Huber-Kaime 3-12U on west side of separator. Calibration shows 4/26/24			
Corrective Action:			Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	216091	Type:	WELL	API Number:	067-07697	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well is PR at time of inspection								
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:	04/10/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0		Fluid Type:					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Fail	Gravel	Pass			
Berms	Pass	Compaction	Pass			

Comment: Erosion on access from private road has erosion

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/27/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Operator needs to seek variance for landowner storing misc equipment and debris on edge of location	welshb	09/06/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200924	location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6695882