

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/06/2024

Submitted Date:

09/06/2024

Document Number:

697010062

FIELD INSPECTION FORMLoc ID 329899 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483367	WELL	DG	04/05/2024		123-51899	CAMENISCH 33-6HZ	WO
483368	WELL	DG	04/06/2024		123-51900	CAMENISCH 33-7HZ	WO
483369	WELL	WO	05/01/2024		123-51901	CAMENISCH 33-2HZ	WO
483370	WELL	DG	04/02/2024		123-51902	CAMENISCH 33-3HZ	WO
483372	WELL	DG	04/04/2024		123-51904	CAMENISCH 33-5HZ	WO
483374	WELL	DG	04/03/2024		123-51906	CAMENISCH 33-4HZ	WO

General Comment:

Location				
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	OTHER			
Comment:	Lease road entrance			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:	32' sound walls			
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	483367	Type:	WELL	API Number:	123-51899	Status:	DG	Insp. Status:	WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	483368	Type:	WELL	API Number:	123-51900	Status:	DG	Insp. Status:	WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	483369	Type:	WELL	API Number:	123-51901	Status:	WO	Insp. Status:	WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	483370	Type:	WELL	API Number:	123-51902	Status:	DG	Insp. Status:	WO
Well Stimulation									
Stimulation Company: Liberty					Stimulation Type: HYDRAULIC FRAC				
Observation:					Other:				
Maximum Casing Recorded: 7220 PSI					Tubing:				
Surface:					Intermediate:				
Production:					Instantaneous Shut-In Pressure (ISIP)				
Bradenhead Psi: 1					Frac Flow Back: Fluid: Gas:				
Comment:									
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	483372	Type:	WELL	API Number:	123-51904	Status:	DG	Insp. Status:	WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	483374	Type:	WELL	API Number:	123-51906	Status:	DG	Insp. Status:	WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Vehicle Tracking	Pass	

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697010063	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6695879