

Inspection Photos
Location: Lola 21-3 TR
Location ID: 309177
API # 05-071-09209



Photo 1 – Well placard on meter house.

Photo 2 – Wellhead and equipment.

Inspection Photos
Location: Lola 21-3 TR
Location ID: 309177
API # 05-071-09209




Photo 3 – Oil stained soils at wellhead

Photo 4 – Pit Flowline in stormwater BMP.

Inspection Photos
Location: Lola 21-3 TR
Location ID: 309177
API # 05-071-09209



Photo 5 – TR pit Facility ID 301194, in the process for closure.

Photo 5 – Unused fencing materials

Inspection Photos
Location: Lola 21-3 TR
Location ID: 309177
API # 05-071-09209



Photo 7 – Pieces of pit liner material on west edge of pit