

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/05/2024

Submitted Date:

09/06/2024

Document Number:

710500342

FIELD INSPECTION FORM

Loc ID 309177 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289596	WELL	PR	05/24/2007	CBM	071-09209	LOLA 21-3 TR	EG
301194	PIT	AC			-	LOLA 21-3 TR	EI

General Comment:

[This is an Environmental Inspection for the Lola 21-3 TR, well location located in Las Animas County CO.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type: UNUSED EQUIPMENT

Comment:

Corrective Action:

Date: 10/18/2024

Overall Good:

Spills:

Type: Area Volume

Lube Oil: WELLHEAD <= 1 bbl

Comment:

Corrective Action:

Date: 10/18/2024

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 289596 Type: WELL API Number: 071-09209 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301194 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: YES Pit ID: 301194 Lat: 37.205140 Long: -104.769000

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: PVC Liner Condition: _____

Comment: Pit Facility ID 301194 is in the closure process under remediation project # 26090
Notify area EPS once pit has been backfilled

Corrective Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	301194	1942017	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500343	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6696205