

Final Reclamation and Stormwater Inspection

Date: 8/28/24

Operator: Bonanza Creek Energy Operating
Company LLC - 8960

Location ID: 332761

Inspection Document #: 713900941

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: DOW-65N63W/28SWNW
Location ID: 332761



Photo 1. The photo is imagery from Operator supplied Document #403596817, CPW Centennial Valley State Wildlife Area Reclamation Report. The photo illustrates an overview of the access roads and facilities in the area under the reclamation plan. Outlined in Red are the facilities that will be associated with this inspection based on Operator determined layouts.

Inspection Photos

Location Name: DOW-65N63W/28SWNW

Location ID: 332761



Photo 2. The photo was taken at the well location facing North. The photo illustrates the location is dominated by weeds and bare soil that is not reflective of reference areas.

Photo 3 The photo was taken at the well location facing East. Refer to the comment for photo 2.

Note - Cultivated wheat and cereal rye was also observed having germinated from what appeared to be the crimped straw.

Inspection Photos

Location Name: DOW-65N63W/28SWNW

Location ID: 332761



Photo 4. The photo was taken at the well location facing South. Refer to the comment for photo 2.

Photo 5. The photo was taken at the well location facing West. Refer to the comment for photo 2.

Inspection Photos

Location Name: DOW-65N63W/28SWNW

Location ID: 332761



Photo 6. The photo was taken along the access road facing Southeast. Refer to the comment for photo 2.