

Final Reclamation and Stormwater Inspection

Date: 8/28/24

Operator: Bonanza Creek Energy Operating
Company LLC - 8960

Location ID: 331414

Inspection Document #: 713900952

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: DOW 34-28
Location ID: 331414



Photo 1. The photo is imagery from Operator supplied Document #403596868, CPW Centennial Valley State Wildlife Area Reclamation Report. The photo illustrates an overview of the access roads and facilities in the area under the reclamation plan. Outlined in Red are the facilities that will be associated with this inspection based on Operator determined layouts.

Inspection Photos
Location Name: DOW 34-28
Location ID: 331414



Photo 2. The photo was taken at the well location facing Northwest. The photo illustrates the location is dominated by weeds and bare soil that is not reflective of reference areas.

Note - Cultivated wheat and cereal rye was also observed having germinated from what appeared to be the crimped straw.



Photo 3 The photo was taken at the well location facing Southeast. Refer to the comment for photo 2.

Inspection Photos
Location Name: DOW 34-28
Location ID: 331414



Photo 4. The photo was taken at the well location facing Southwest. Refer to the comment for photo 2.



Photo 5. The photo was taken at the well location facing Northeast. Refer to the comment for photo 2.

Inspection Photos
Location Name: DOW 34-28
Location ID: 331414



Photo 6. The photo was taken at the boundary of the well location facing Northwest. The photo illustrates the boundary of the location disturbance and reference areas.