

**Operator: 8 North**

**Location Name: DF RANCH-611N61W 15SENE**

**Loc ID: 310707**

**Inspection: 696300873**







**CA:** Stained Soil at Wellhead, Exhaust, and Gas Engine. See photos 2, 3, 4, 5. Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e  
**CA Resolution:** Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed.