

## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618



Photo # 8261 From Entrance to location



Photo # 8262 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618



Photo # 8263 Location



Photo # 8264 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618




Photo # 8265 Location



Photo # 8266 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618




Photo # 8267 Location



Photo # 8268 Debris

## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU Federal 24-13A1 (D25W) Pad

Location #: 334618



Photo # 8269