

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/04/2024

Submitted Date:

09/09/2024

Document Number:

713400297

FIELD INSPECTION FORMLoc ID 335937 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, CAERUS		cogcc.inspections@caerusoilandgas.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292360	WELL	TA	09/01/2022	GW	045-14699	DWU CP11D-33 M33 49	TA

General Comment:**CECMC Inspection Report Summary**

On 9/4/2024 at approximately 12:30, Compliance Inspector Dusty Popejoy conducted an on-site inspection for a plugging operation at CAERUS PICEANCE LLC NPM/M33-496 Pad at Location ID #335937 in Garfield County, Colorado.

While there, I observed wireline perforating at 102' on DWU #CP11D-33 M33 49 well. Document #'s 403897958 & 403897967

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

Signs/Marker:

1- Location is missing wellhead signage with a CA date of 10/9/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Limited inspection due to ongoing plugging operations on location.

Any Corrective Actions from previous Inspections are still applicable.

Location

Lease Road:			
Type	Access		
comment:	Access.		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Sign at entrance to location.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Location is missing wellhead signage.		
Corrective Action:	Comply with CECMC Signage rules.	Date:	10/09/2024

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	Accumulator.		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Rig tanks.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wireline truck.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Workover rig.		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Dog houses.		
Corrective Action:		Date:	
Type: Other	# 1		

Comment: Rig pump.				
Corrective Action:			Date:	
Type: Other	# 2			
Comment: Frac tanks - fresh water				
Corrective Action:			Date:	
Type: Other	# 1			
Comment: Cement truck.				
Corrective Action:			Date:	

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 292360

Type: WELL

API Number: 045-14699

Status: TA

Insp. Status: TA

Cement

Cement Contractor

Contractor Name: DUCO

Contractor Phone:

Surface Casing

Cement Volume (sx):

Circulate to Surface:

Cement Fall Back:

Top Job, 1" Volume:

Intermediate Casing

Cement Volume (sxs):

Good Return During Job:

Production Casing

Cement Volume (sx):

Good Return During Job:

Plugging Operations

Depth Plugs(feet range):

Cement Volume (sx):

Good Return During Job:

Cement Type:

Comment:

9/4/2024 at approximately 13:00 hours observed wireline perforating at 102'.
Please refer to document #'s 403897958 & 403897967

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400298	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6697515

Date Run: 9/9/2024 Doc [#713400297]

Page 4 of 4