

Inspection Photos

08/22/2024

Operator: BEEMAN OIL & GAS INC - 7125

Location ID: 425419

Inspection Doc: 696206205

Moffat County, CO

Aaron Trujillo
Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



August 22, 2024



August 22, 2024

Photo 1: Photos 1-2 taken from the Location entrance, on the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west. Photos also shows Undesirable Plant Species established throughout the working pad surface of the Location; including Kochia, Russian thistle, Prostrate Knotweed, Scotch thistle, etc...



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



August 22, 2024



August 22, 2024

Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



August 22, 2024



August 22, 2024

Photo 3: Photos 3 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, west to northwest. Photos also shows Undesirable Plant Species established throughout the working pad surface of the Location; including Kochia, Russian thistle, Prostrate Knotweed, Scotch thistle, etc...



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 5: Photo taken from the northeast end of the working pad surface. Photo shows stockpile of material stored on Location. Photo also shows that BMPs to protect the stockpile from wind/water erosion, BMPs to minimize sediment transport, and BMPs to protect stockpile from weed establishment are missing or insufficient. BMPs required pursuant to Rule 1002.c and 1002.f, or, If materials are not necessary, materials require removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 6: Photo taken from the tank battery facility on the north end of the Location, facing south. Photo shows signage at the facility has been installed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 7: Photo taken from the tank battery facility on the north end of the Location, facing north. Photos examples showing information pursuant to Rule 605.h (NFPA Label, Capacity information) has not been posted.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 8: Photo taken from the tank battery facility on the north end of the Location. Photo shows line at tank has not been capped or plugged.

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419




Photo 9: Photos taken from the well/pumpjack. Photo left show well signage has been posted pursuant to Rule 605.d



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 10: Photo left taken during the 5/8/2023 inspection. Inspection noted that the guard was not installed on the pumpjack. Operator submitted a Resolution stating guard was replaced. Photo right taken 8/22/2024 and show guard remains improperly stored, and has not been replaced.

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 11: Photo taken from the west end of the Location facing southeast. Photo shows cut slopes have been recontoured. Vegetation establishing on the slopes are predominantly undesirable plant species.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 12: Photos taken from the top of the cut slopes along the west end of the Location. Photos examples showing Noxious Weed establishment (Scotch thistle, Houndstongue). Weed management efforts have not been performed, or has been insufficient.

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 13: Photo taken from the west end of the Location, facing southeast. Photo shows areas of the Location where interim reclamation does not appear to have been performed. Vegetation is predominantly Undesirable Plant Species such as Cheatgrass, Field Pennycress, etc...



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 14: Photos taken from the top of the fill slopes on the south end of the Location, facing northwest and north. Revegetation efforts have not been performed, or have failed; desirable plant germination/establishment was not observed within the recently reclaimed areas. Vegetation within photos are predominantly Undesirable and Noxious Plant Species. Unable to find evidence that soils had been "crimped" with any materials such as mulch. BMPs along slopes have either not been implemented or not maintained until long-term stabilization is achieved; slopes remain predominantly bare.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 15: Continued from photo 14. Desirable plant germination/establishment was not observed within the recently reclaimed areas. Vegetation establishing within the interim areas are predominantly Undesirable and Noxious Plant Species, including Scotch thistle (arrow).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 16: Photos taken from the interim areas/fill slopes on the east end of the Location, facing northwest. Revegetation efforts have not been performed, or have failed; desirable plant germination/establishment was not observed within the recently reclaimed areas. Vegetation within photos are predominantly Undesirable and Noxious Plant Species. Unable to find evidence that soils had been "crimped" with any materials such as mulch. BMPs along slopes have either not been implemented or not maintained until long-term stabilization is achieved; slopes remain predominantly bare.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 17: Photos taken from the interim areas/fill slopes on the east end of the Location, facing northwest. Photo shows boundary of the reclaimed areas, and vegetation at the toe of the slope. See comments under photo 16.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 18: Photos taken from the east end of the Location. Photos show Noxious Weeds (Scotch thistle) have continued to spread and establish on the fill slopes and berms of the Location. Weeds are also spreading onto the adjacent, off-location areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 19: See comments under photo 18.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 20: Photo left from the 5/8/2023 inspection. Photo right from the 8/22/2024 inspection. Photo example showing trash debris remaining



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 21: Photos 21-22 taken from the access road. Photos show weeds (Russian thistle, Kochia, Scotch thistle) have continued to spread and establish along the access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: BEEMAN OIL & GAS INC - 7125

Location ID: 425419



Photo 22: See comments under photo 21.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources