

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/09/2024

Submitted Date:

09/09/2024

Document Number:

715200925

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
433700 _____ Welsh, Brian _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96340
Name of Operator: WIEPKING-FULLERTON ENERGY LLC
Address: PO BOX 460928
City: DENVER State: CO Zip: 80246

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Quint, Craig		craig.quint@state.co.us	
Wambach, Hayden	(303) 514-0757	haydenw@taqenergy.com	
Shalberg, Greg		gregshalberg@aol.com	
Sanchez, Chris		chris.sanchez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433688	WELL	PR	11/01/2020	OW	073-06546	Ma-State 4	PR

General Comment:

On 9/9/24 SE Compliance Specialist Brian Welsh responded to a heated tank fire which was communicated by his immediate supervisor. Detailed in this inspection, is the findings and analysis of the equipment damaged and proper procedure for remediation. Operator contacted Eastern Area Compliance Supervisor to notify of the fire

Location

Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action		Date:	

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:	Stickers on chemical tanks		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign by tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks. Labeling on burnt tank will need to be replaced		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil	Tank	>= 5 bbls	
Comment:	Spill was related to a tank fire from the fire tube (see comments in Tank and Berms). Free fluid has already been removed. Oil spill was isolated to 1 tank (290115)		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Report spill or release of E&P waste or produced fluids. Contact ECMC EPS staff per Rule 912.b.		Date: <u>09/10/2024</u>

In Containment: Yes
 Comment: _____
 Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit, wellhead and line heater		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Metal panels and wire fence around tanks, treaters, ECDs amd flare		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	300 BBLs	HEATED STEEL AST		39.162125,-103.619347
Comment:	Central tank battery for (Ma-State 1,4,6,10,12S,12X,13). The middle tank (290115) fire tube had a leak and caught on fire, subsequently melting the temperature guage on the east oil tank (290114) and burning that fire tube. Tank heaters on 2 tanks were destroyed in the fire. Tanks are still operable for continued production. Inspector spoke with Roustabout foreman and fire tubes will be replaced and remediation will begin on 9/10/24				
Corrective Action:					Date:

Paint	
Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Berms have plastic liner under the rocks				
Corrective Action:					Date:

Venting:		
Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:		
Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 433688 Type: WELL API Number: 073-06546 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central tank battery for \(Ma-State 1,4,6,10,12S,12X,13\) 1220' W @ 39.162125/-103.619347](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Inspector spoke with pumper and remediation will begin on 9/10/24	welshb	09/09/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715200927	Tank battery pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6699140