

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2024

Submitted Date:

09/03/2024

Document Number:

715200848**FIELD INSPECTION FORM**Loc ID 306879 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-------------------------------|--------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| , General | 970-749-4139 | sjninspections@ikavenergy.com | All SW Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 272253 | WELL | PR | 08/31/2004 | CBM | 067-08948 | LE PLATT 2 | PR |

General Comment:

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

Location

| | | | |
|--------------------|--|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Gravel road. Access is at the end of CR 509B | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Sticker on water tank has peeled off and needs replaced. Sticker on separator | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 09/29/2024 |
| Type | WELLHEAD | | |
| Comment: | Lease sign by fence | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|--|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | Metal panels around water tank, separator, meter shed and telemetry equipment | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Meter shed on west side of separator. Calibration shows 7/10/24 | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | Bird protector on separator stack | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 1 | | |
| Comment: | Vertical heated separator on west side of water tank. Built in fluid storage | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Plumbed to surface | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------------|--|-------|
| Type: Ancillary equipment | # 1 | |
| Comment: | Telemetry equipment on west side of meter shed | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | OTHER | BV STEEL | | 37.227990,-107.611280 |
| Comment: | 95bbl buried steel water tank on southeast corner of location | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 95bbls | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|------------------------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | Steel ring containment | | | |
| Corrective Action: | | | Date: | |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|-------------------------|----------------------------------|-------|------------------------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 272253 | Type: | WELL | API Number: | 067-08948 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well is PR at time of inspection | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | 07/09/2024 | | Annual Brhd Completed? | Yes | | | | | |
| Last Brhd Test Results | Initial Surf Csg Pressure: | 3 | Fluid Type: | | | | | | |
| | End Surf Csg Pressure: | 0 | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403908561 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691921 |
| 715200879 | location photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691888 |