



FORM  
INSP  
  
Rev  
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
08/30/2024  
Submitted Date:  
09/10/2024  
Document Number:  
708302708

FIELD INSPECTION FORM

Loc ID  
334415

Inspector Name:  
Morris, Matthew

On-Site Inspection ☐

2A Doc Num: \_\_\_\_\_

Operator Information:

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

☒ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, CAERUS		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296553	WELL	PR	07/01/2018	GW	045-16074	BATTLEMENT MESA 26-22D	PR
296577	WELL	PR	06/01/2023	GW	045-16075	BATTLEMENT MESA 26-12B	PR
296579	WELL	SI	02/01/2024	GW	045-16076	BATTLEMENT MESA 26-12C	SI
296582	WELL	PR	09/01/2014	GW	045-16077	BATTLEMENT MESA 26-12D	PR
296586	WELL	SI	02/01/2024	GW	045-16078	BATTLEMENT MESA 26-13A	SI
296591	WELL	PR	07/01/2018	GW	045-16079	BATTLEMENT MESA 26-13B	PR
296594	WELL	PR	09/01/2017	GW	045-16080	BATTLEMENT MESA 26-13C	PR
296596	WELL	PR	09/01/2017	GW	045-16081	BATTLEMENT MESA 26-13D	PR
296603	WELL	PR	07/01/2018	GW	045-16082	BATTLEMENT MESA 26-14A	PR
296604	WELL	SI	04/01/2024	GW	045-16083	BATTLEMENT MESA 26-23A	SI
296605	WELL	PR	08/01/2020	GW	045-16084	BATTLEMENT MESA 26-23B	PR
296606	WELL	SI	04/01/2024	GW	045-16085	BATTLEMENT MESA 26-23C	SI
296607	WELL	SI	04/01/2024	GW	045-16086	BATTLEMENT MESA 26-22B	SI
296608	WELL	PR	09/14/2009	GW	045-16087	BATTLEMENT MESA 26-22C	PR

General Comment:

Date Run: 9/10/2024 Doc [#708302708]

Page 1 of 9

#### CECMC Inspection Report Summary

On 8/30/2024 at approximately 14:00, Compliance Inspector Matthew Morris conducted a follow-up inspection at CAERUS PICEANCE LLC, Battlement Mesa/26K-795 at Location ID #334415 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Stored equipment in tank battery
- 2) Unsecured separator poses a wildlife entry hazard
- 3) Unsecured manway on condensate tank poses a wildlife entry hazard

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/(970)285-2615

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Stored equipment in tank battery.		
Corrective Action:	Remove stored equipment to comply with Rule 606.	Date:	09/17/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Hog panels/cattle panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	ECD protected by cattle panels.		
Corrective Action:		Date:	

Type	OTHER		
Comment:	Pig station protected by pipe rails.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 14		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 14		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 14		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:	Unsecured separator poses a wildlife entry hazard.		
Corrective Action:	Secure equipment to comply with Rule 608.e.		Date: 09/15/2024
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Morris, Matthew

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)	500 gal				
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	7	400 BBLs	STEEL AST		,
Comment:	Unsecured manway on southeast tank in battery poses a wildlife entry hazard.				
Corrective Action:	Secure equipment to comply with Rule 608.e.				Date: 09/15/2024
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
<u>Venting:</u>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	296553	Type:	WELL	API Number:	045-16074	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	296577	Type:	WELL	API Number:	045-16075	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	296579	Type:	WELL	API Number:	045-16076	Status:	SI	Insp. Status:	SI
<b>Idle Well</b>									
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____						
Comment:	Last produced January 2024 per production report.								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	296582	Type:	WELL	API Number:	045-16077	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	296586	Type:	WELL	API Number:	045-16078	Status:	SI	Insp. Status:	SI
<b>Idle Well</b>									
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____						
Comment:	Last produced January 2024 per production report.								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	296591	Type:	WELL	API Number:	045-16079	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	296594	Type:	WELL	API Number:	045-16080	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:						Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296596 Type: WELL API Number: 045-16081 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296603 Type: WELL API Number: 045-16082 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296604 Type: WELL API Number: 045-16083 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In☐ Temporarily Abandoned

Reminder:

Comment: Last produced March 2024 per production report.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296605 Type: WELL API Number: 045-16084 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296606 Type: WELL API Number: 045-16085 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In☐ Temporarily Abandoned

Reminder:

Comment: Last produced March 2024 per production report.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296607 Type: WELL API Number: 045-16086 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In☐ Temporarily Abandoned

Reminder:

Comment: Last produced March 2024 per production report.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296608 Type: WELL API Number: 045-16087 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12



Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
		Ditches				
		Compaction				
Gravel						
		Sediment Traps				
Compaction						
Berms						
		Rip Rap				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302709	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6699681">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6699681</a>