

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/28/2024

Submitted Date:

08/30/2024

Document Number:

693807699

FIELD INSPECTION FORM

Loc ID: 316836 Inspector Name: BROWNING, CHUCK On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10841
Name of Operator: AMERICAN HELIUM OPERATING LLC
Address: 600 TRAVIS STREET SUITE 5050
City: HOUSTON State: TX Zip: 77002

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|-----------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |
| Demarco, Jaime | | jdemarco@blm.gov | |
| Gavito, Danielle | 303-524-4651 | dgavito@americanhelium.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 266587 | WELL | SI | 09/01/2022 | GW | 113-06122 | ANDY'S MESA FEDERAL 29 | SI |

General Comment:

ECMC staff performed a routine field inspection on 8/28/2024.
Issues were found requiring corrective action. See inspection text and photos for details.
Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Operator and emergency contact nuber corrected 8-30-29. Sign is faded needing replaced.

Sign on order 9-9-24 for replace. *Danny L White* 9-8-24

New sign replaced on meter 9-10-24. Please see photo's. *Danny L White* 9-10-24

Placards installed on production tanks. 9-10-24. Please see attached photo.

Danny L White 9-10-24

| Location | | | |
|--|--|--------|------------------|
| Lease Road: | | | |
| | Type Access | | |
| comment: | | | |
| Corrective ActionL | | | Date: |
| | Type Main | | |
| comment: | | | |
| Corrective ActionL | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| | Type WELLHEAD | | |
| Comment: | Sign on meter housing. Sign not legible | | |
| Corrective Action: | Install sign to comply with Rule 605.g | | Date: 09/30/2024 |
| | Type TANK LABELS/PLACARDS | | |
| Comment: | Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | | Date: 09/30/2024 |
| Emergency Contact Number: | | | |
| Comment: | 435-631-2239 | | |
| Corrective Action: | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| | Type WELLHEAD | | |
| Comment: | Panel fence | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Deadman # & Marked | # 4 | | corrective date |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |

AM 29 well location ID signage at meter. New Sign on order 9-9-24



AM 29 location ID signage at Meter replaced 9-10-24



Placards installed on production tanks. 9-10-24



| | | | |
|-----------------------|-----|-------|--|
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| PRODUCED WATER | 1 | 300 BBLs | STEEL AST | | 38.057742,-108.658630 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CONDENSATE | 1 | 100 BBLs | PBV STEEL | | 38.057742,-108.658630 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 266587 Type: WELL API Number: 113-06122 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well shut in 9/2022. Last MIT 1/8/2015.
Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42.
Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. Date: 09/30/2024

BradenHead

Date of Last Brhd Test: 09/16/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 20 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | Gravel | Pass | | | |
| Gravel | Pass | Ditches | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------------------|---|
| 403907232 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6689592 |
| 693807700 | Inspection photos 8/28/2024. | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6689578 |