

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/28/2024

Submitted Date:

08/30/2024

Document Number:

693807695

FIELD INSPECTION FORMLoc ID 316833 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10841

Name of Operator: AMERICAN HELIUM OPERATING LLC

Address: 600 TRAVIS STREET SUITE 5050

City: HOUSTON State: TX Zip: 77002

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Demarco, Jaime		jdemarco@blm.gov	
Labowskie, Steve		steve.labowskie@state.co.us	
Gavito, Danielle	303-524-4651	dgavito@americanhelium.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264710	WELL	SI	06/01/2022	GW	113-06109	FOSSIL FEDERAL 1-20	SI

General Comment:

ECMC staff performed a routine field inspection on 8/28/2024.

Issues were found requiring corrective action. See inspection text and photos for details.

Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location ID signage addressed on FF 1-20. Please see photo. New sign on order 9-9-24 for replace.

Danny L White 9-8-24

Location ID sign replaced 9-10-24. Please see photo's.

Placard installed on FF 1-20 production tank. 9-10-24. Please see photo.

Danny L White 9-10-24

Location**Lease Road:**

Type	Main		
comment:			
Corrective Action	L	Date:	
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/30/2024

Emergency Contact Number:

Comment:	435-631-2239		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Pipe barricade		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

FF 1-20 location ID signage on meter. 9-8-24



New location Sign installed on meter. 9-10-24



Placards installed on FF 1-20 production tank. 9-10-24



Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	100 BBLS	PBV STEEL		38.062666,-108.659364
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		38.062768,-108.659354
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

AirsID

<u>Wells Served By Facilities Above</u>		API Number	AirsID
API Number			
113-06109			
113-06144			
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities										
Facility ID:	264710	Type:	WELL	API Number:	113-06109	Status:	SI	Insp. Status:	SI	
Idle Well										
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:		<div>Well shut in 6/2022. No MIT on record. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.</div>								
Corrective Action:		<div>Produce well after performing successful mechanical integrity test per Rule 417 or plug well.</div>					Date:			09/30/2024
BradenHead										
Date of Last Brhd Test:		09/16/2023		Annual Brhd Completed?		Yes				
Last Brhd Test Results		Initial Surf Csg Pressure:		20		Fluid Type:		NONE		
		End Surf Csg Pressure:		0						
Comment:		<div></div>								
Corrective Action:		<div></div>					Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			
Gravel	Pass	Ditches	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403907231	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6689591
693807696	Inspection photos 8/28/2024	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6689576