

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/26/2024

Submitted Date:

09/04/2024

Document Number:

715200810

FIELD INSPECTION FORM

Loc ID 333448 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General	970-749-4139	sjninspections@ikavenergy.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285376	WELL	PR	08/25/2021	CBM	067-09195	MOSKETTI 43-33 3	PR

General Comment:

SE Compliance Specialist Brian Welsh conducted a field inspection of the well location and equipment

Location			
Lease Road:			
Type	Access		
comment:	Gravel road off of CR 311		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on steel containment. Sticker on separator		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by gate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Metal panels around buried tank, separator and meter shed		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal panels around wellhead and pumping unit for the Mosketti 43-33 3. Metal cage around base and gear box for the Mosketti 43-33 1		
Corrective Action:		Date:	
Equipment:			
Type: Bradenhead	# 2		corrective date
Comment:	PVC bradenhead access for both wells		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Telemetry equipment and power transformer on southeast corner of location, electric panels at units		
Corrective Action:		Date:	

Type: Prime Mover	# 2	
Comment:	Electric motors	
Corrective Action:		Date:
Type: Pump Jack	# 2	
Comment:	Weatherford 228 for Mosketti 43-33 3. American 320 for Mosketti 43-33 1	
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:	Shared meter shed for Mosketti 43-33 1 & 3 next to separator	
Corrective Action:		Date:
Type: Vertical Heated Separator	# 2	
Comment:	2-Vertical heated separators on east side of buried tank in metal shed	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:	Bird protector on separator stack	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.145500,-107.717700
Comment:	Partially buried steel tank on west side of separators				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95bbbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Steel ring containment			
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
067-07777
067-09195

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
------	--

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 285376 Type: WELL API Number: 067-09195 Status: PR Insp. Status: PR

Producing Well

Comment: Well is PR at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/16/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

09/26/2024

Corrective Action:

Make bradenhead monthly monitoring reports available to COGCC per Rule 419.b.(5)

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Gravel	Pass	Gravel	Pass			
Rip Rap	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403909747	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693195
715200892	location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693188