

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2024

Submitted Date:

09/04/2024

Document Number:

715200817**FIELD INSPECTION FORM**Loc ID 333401 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**ECMC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General	970-749-4139	sjninspections@ikavenergy.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215007	WELL	PR	01/12/1983	CBM	067-06612	HANSTEDT 07U-01 1	PR

General Comment:[SE Compliance Specialist Brian Welsh conducted a routine field inspection of the wellhead.](#)[Associated equipment for the well is listed on Hanstedt 07U-01 3 inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Gravel road off of CR 222 through scrap yard		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by gate at entrance		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead. Metal cage around gearbox		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	215007	Type:	WELL	API Number:	067-06612	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well is PR at time of inspection								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	05/05/2023		Annual Brhd Completed?	No					
Last Brhd Test Results	Initial Surf Csg Pressure:	4	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:				09/26/2024					
Corrective Action:	Make bradenhead monthly monitoring reports available to COGCC per Rule 419.b.(5)			Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403909828	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693302