

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2024

Submitted Date:

09/04/2024

Document Number:

715200829**FIELD INSPECTION FORM**Loc ID 334196 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General	970-749-4139	sjninspections@ikavenergy.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214951	WELL	PR	06/01/2016	CBM	067-06556	MAYFIELD 11U-01 1	PR

General Comment:[SE Compliance Specialist Brian Welsh](#) conducted a routine field inspection of the well location and equipment

Location

Lease Road:			
Type	Access		
comment:	Gravel road off of CR 510		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on separator and meter shed. Sticker has peeled off of metal containment at water tank and needs to be replaced		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/27/2024
Type	WELLHEAD		
Comment:	Lease signs by fence at Mayfield 11U-01 3		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Metal panels around water tank, separators, meter shed and telemetry equipment		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 2		
Comment:	PVC bradenhead access		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Transformer on north side of location, control panel, telemetry equipment on west side of meter shed, cathodic protection on east side of water tank		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:	2-Vertical heated separators with metal shed on west side of water tank		
Corrective Action:		Date:	

Type: Bird Protectors	# 1		
Comment:	Bird protector on separator stack		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:	Shores C80 for Mayfield 11U-01 1. Linear rod pump for the Mayfield 11U-01 3		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Shared meter run for Mayfield 11U-01 1&3 on west side of separator. Calibration shows 5/2/24		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric motors		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV STEEL		37.202980,-107.691310	
Comment:	95bbls buried steel tank on northeast side of location					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Steel ring containment			
Corrective Action:				
		Date:		

Wells Served By Facilities Above

API Number
067-06556
067-09469

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	214951	Type:	WELL	API Number:	067-06556	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well is PR at time of inspection								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	07/25/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	1		Fluid Type:					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403910140	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693558
715200897	location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693556