

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2024

Submitted Date:

09/04/2024

Document Number:

715200831**FIELD INSPECTION FORM**Loc ID 333442 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**ECMC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**18 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General	970-749-4139	sjninspections@ikavenergy.com	All SW Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284287	WELL	PR	08/01/2018	CBM	067-09137	GEORGE 11-11 3	PR

**General Comment:**SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road off of CR 510		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank. Stickers on separators		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease signs at location entrance		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Metal panels around telemetry on south side of meter sheds		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal panels around wellhead and control panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Metal panels around water tank, separators and meter sheds		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 2		
Comment:	2-Linear rod pumps		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	2-Meter sheds by separators. Calibration shows 5/2/24		
Corrective Action:		Date:	

Inspector Name: Welsh, Brian

Type: Ancillary equipment	# 4		
Comment:	2-control panels and 2-telemetry equipment		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:	Not all deadmen are marked		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	09/27/2024
Type: Prime Mover	# 2		
Comment:	2-Electric motors		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	Bird protectors on separator stacks		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:	1-Vertical heated separator with metal shed for George 11-11 3 (west separator) 1-Vertical heated separator on west side of water tank (east separator)		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	PVC bradenhead access for both wells		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	BV STEEL		37.209730,-107.692950	
Comment:	95bbl buried steel water tank on east side of location					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	95bbls	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Wells Served By Facilities Above**

API Number
067-09137
067-07686

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No		
--------	--	--

Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

Type		
Comment:		
Corrective Action:		Date:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	284287	Type:	WELL	API Number:	067-09137	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well is PR at time of inspection								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	07/25/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0		Fluid Type:					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403910142	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693559">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693559</a>
715200896	location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693557">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6693557</a>