

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2024

Submitted Date:

09/04/2024

Document Number:

715200851**FIELD INSPECTION FORM**Loc ID 326663 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**ECMC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General	970-749-4139	sjninspections@ikavenergy.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261666	WELL	PR	12/02/2002	CBM	067-08655	JOE MARTIN 2	PR

General Comment:[SE Compliance Specialist Brian Welsh](#) conducted a routine field inspection of the well location and equipment

Location**Lease Road:**

Type	Access		
comment:	Gravel road off of CR 506. Combination lock on gate. Walked into location to conduct field inspection		
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Lease sign at edge of location		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank. Stickers on separator and meter shed are peeling off and need replaced		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	10/29/2024

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Metal panels around water tank, separator and meter shed		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 1		corrective date
Comment:	Meter shed on east side of separator. Calibration shows 7/1/24		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Bird protector on separator stack		
Corrective Action:		Date:	

Type: Bradenhead	# 1	
Comment:	Bradenhead access at surface	
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	Telemetry equipment on northeast corner of location. Cathodic protection riser on west side of telemetry equipment	
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:	Vertical heated separator on east side of water tank	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.228140,-107.621080
Comment:	95bbl buried steel water tank on north side of location				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Steel ring containment			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	261666	Type:	WELL	API Number:	067-08655	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well is SI at time of inspection								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	06/28/2023		Annual Brhd Completed?	No					
Last Brhd Test Results	Initial Surf Csg Pressure:	5	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:	Make bradenhead monthly monitoring reports available to COGCC per Rule 419.b.(5)								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
Berms	Pass					
Rip Rap	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403909342	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692812
715200883	Location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692797