

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/04/2024

Submitted Date:

09/04/2024

Document Number:

717700384**FIELD INSPECTION FORM**Loc ID 444757 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444771	WELL	PR	06/18/2018	OW	123-42744	Anschutz Equus Farms 4-62-28-4841C2	PR

General Comment:[This is an audit on the well](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well name sign at the well doesn't reflect what is in the ECMC data base. Submit proper documentation and correct designated well sign.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	12/31/2024

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 444771

Type: WELL

API Number: 123-42744

Status: PR

Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/19/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<div>ECMC Inspection Report Summary</div> <div>On Tuesday, August27, 2024, at approximately 10:40 AM, Inspector Adam Burns conducted an on-site inspection at the following location:</div> <div>Well: Anschutz Equus Farms 4-62-28-4841C2</div> <div>Operator: Civitas</div> <div>API: 05-123-42744</div> <div>County: Weld</div> <div>During the inspection, a producing well was observed. The following possible compliance issues were identified:</div> <div>Incorrect Well Name: Well name sign at the well doesn't reflect what is in the ECMC data base. Submit proper documentation and correct designated well sign. Install sign to comply with Rule 605.d.</div> <div>A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules.</div> <div>Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</div>	burnsa	09/04/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403909030	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692552
717700385	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692539