

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2024

Submitted Date:

09/04/2024

Document Number:

708302682**FIELD INSPECTION FORM**Loc ID 335601 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285292	WELL	SI	04/01/2024	GW	045-12419	AP 34-8-695	SI
296194	WELL	SI	04/01/2024	GW	045-15925	ALLEN POINT 644-8-695	SI
296657	WELL	SI	04/01/2024	GW	045-16089	AP 321-17-695	SI
296658	WELL	SI	04/01/2024	GW	045-16090	AP 331-17-695	SI
296659	WELL	SI	04/01/2024	GW	045-16091	AP 614-8-695	SI

**General Comment:****CECMC Inspection Report Summary**

On 8/29/2024 at approximately 13:40, Compliance Inspector Matthew Morris conducted a follow-up inspection at TEP ROCKY MOUNTAIN LLC, AP-66S95W/8SWSE at Location ID #335601 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Open-ended drop lines to pit pose a wildlife entry hazard
- 2) Stored supplies on location

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Stored cattle panels on location.		
Corrective Action:	Remove stored supplies to comply with Rule 606.	Date:	07/10/2024
Type	OTHER		
Comment:	Multiple open-ended drop lines to pit pose a wildlife entry hazard.		
Corrective Action:	Secure lines to comply with Rule 608.e.	Date:	07/08/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Type	PIT		
Comment:	Hog panels/netting		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 12		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type) _____							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficent		Adequate	
Comment:							
Corrective Action:							Date: _____
Contents	#	Capacity	Type		Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	HEATED STEEL AST			,	
Comment:							
Corrective Action:							Date: _____
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)		210 bbls					
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficent		Adequate	
Comment:							
Corrective Action:							Date: _____
Contents	#	Capacity	Type		Tank ID	SE GPS	
METHANOL	1	OTHER	STEEL AST			,	
Comment:							
Corrective Action:							Date: _____
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)		500 gal					
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficent		Adequate	
Comment:							
Corrective Action:							Date: _____
Contents	#	Capacity	Type		Tank ID	SE GPS	
CONDENSATE	2	400 BBLs	HEATED STEEL AST			,	
Comment:							
Corrective Action:							Date: _____
<u>Paint</u>							
Condition	Adequate						

Other (Content)	
Other (Capacity)	
Other (Type)	

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	

Comment:		
Corrective Action:		Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	400 BBLS	STEEL AST		,	

Comment:				
Corrective Action:			Date:	

Condition		
-----------	--	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		
Corrective Action:		Date:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 285292 Type: WELL API Number: 045-12419 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last produced March 2024 per production report.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296194 Type: WELL API Number: 045-15925 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last produced March 2024 per production report.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296657 Type: WELL API Number: 045-16089 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last produced March 2024 per production report.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296658 Type: WELL API Number: 045-16090 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last produced March 2024 per production report.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 296659 Type: WELL API Number: 045-16091 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last produced March 2024 per production report.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
		Compaction				
Gravel						
		Sediment Traps				
		Ditches				
		Rip Rap				
Berms						
		Gravel				
Compaction						

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403909414	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692871">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692871</a>
708302683	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692869">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692869</a>